Beach Access Repairs and Upgrades

Stairway Replacement

Pine Ave
Walnut Ave
Sycamore Ave
Chestnut Ave
Cherry Ave
Juniper Ave
Hemlock Ave
Redwood Ave
Redwood Ave
Sequoia Ave
Chinquapin Ave
Chinquapin Ave
Aqua Hedionda
Lagoon

Upper Sidewalk Repairs



Source: Google Earth Pro

Lower Sidewalk Repairs as Needed