



BUILDING INSPECTIONS - Scheduled 4-24-2024

These inspection times are **APPROXIMATE** and **based on a 2 hour window upon the inspectors anticipated schedule.**
The next city holiday is Monday, May, 27th, 2024 and no work is allowed. Inspection requests for Tuesday, May 28th, 2024, must be received by Friday, May 24th, 2024, by 2:00 p.m.
Any requests received after 2:00 p.m. will be scheduled on Wednesday, May 29th, 2024.

*****SOLAR INSPECTIONS, EMAIL OFFICE WHEN PHOTOS ARE UPLOADED TO CSS PORTAL*****

Pending Inspections

CBR2023-3710	6830 ALDERWOOD DR	No	SW	BLDG-35 Solar Panel
CBR2024-0507	4736 BRYCE CIR	No	NW	BLDG-35 Solar Panel
CBRA2021-0133	3646 CARLSBAD BLVD	No	NW	BLDG-Planning Final
CBR2024-0699	3986 FOOTHILL AVE	No	NE	BLDG-35 Solar Panel
CBR2024-0454	3145 SALINA RD	No	NE	BLDG-35 Solar Panel
CBR2024-0023	3821 SKYLINE RD	No	NW	BLDG-35 Solar Panel
CBR2024-0229	830 SKYSAIL AVE	No	SW	BLDG-35 Solar Panel
CBR2024-0651	6899 TRADEWINDS DR	No	SW	BLDG-35 Solar Panel
CBR2023-5072	2732 UNICORNIO ST	No	SE	BLDG-Final Inspection

PERMIT NUMBER	STREET	VIRTUAL	TIME BEGIN	INSPECTION TYPE
Chris Renfro 760-331-7048				
CBR2024-0515	2826 ANDOVER AVE	No	9:00	BLDG-24 Rough/Topout
CBR2021-2810	3325 CABO WAY, # 2	No	2:00	BLDG-SW-Pre-Con
CBR2022-4738	2528 EL GAVILAN CT	No	1:00	BLDG-Final Inspection
CBR2023-5140	7345 GABBIANO LN	Yes	1:00	BLDG-54 Equipotential Bond(Pc
CBR2024-0631	3658 HARWICH DR	No	10:00	BLDG-33 Service Change/Upgr.
CBRA2019-0341	4246 HILLSIDE DR	No	12:00	BLDG-25 Water Heater/Vents

CBRA2020-0209	4246 HILLSIDE DR			BLDG-25 Water Heater/Vents
CBR2024-0618	3531 MILFORD PL	No	10:00	BLDG-24 Rough/Topout
CBR2024-0670	7011 NUTMEG WAY	No	12:00	BLDG-Final Inspection
CBRA2023-0134	4827 PARSLEY LN	No	9:00	BLDG-84 Rough Combo(14,24,
CBRA2023-0135	4833 PARSLEY LN			BLDG-84 Rough Combo(14,24,
CBRA2023-0136	4839 PARSLEY LN			BLDG-84 Rough Combo(14,24,
CBRA2023-0038	2670 ROOSEVELT ST	No	11:00	BLDG-14 Frame/Steel/Bolting/\
CBRA2023-0039	2672 ROOSEVELT ST			BLDG-14 Frame/Steel/Bolting/\
CBRA2023-0040	2674 ROOSEVELT ST			BLDG-14 Frame/Steel/Bolting/\
CBC2022-0188	2598 STATE ST	No	11:00	BLDG-17 Interior Lath/Drywall
CBRA2022-0068	3865 SYDNEY WAY	No	12:00	BLDG-Final Inspection

Dirk de Roggenbuke 442-977-4628

CBR2023-2165	7906 CALLE SAN FELIPE	No	11:00	BLDG-18 Exterior Lath/Drywall
CBR2023-2165	7906 CALLE SAN FELIPE			BLDG-84 Rough Combo(14,24,
CBR2024-0835	3444 CAMINO LARGO	No	12:00	BLDG-43 Air Cond./Furnace Se
CBR2024-0835	3444 CAMINO LARGO			BLDG-Final Inspection
CBR2023-4641	7526 CAMINO MINERO	No	10:00	BLDG-24 Rough/Topout
CBR2023-4641	7526 CAMINO MINERO			BLDG-34 Rough Electrical
CBR2024-0263	3580 CORTE CASTILLO	No	10:00	BLDG-43 Air Cond./Furnace Se
CBR2024-0263	3580 CORTE CASTILLO			BLDG-Final Inspection
CBR2023-2958	6749 LONICERA ST	No	9:00	BLDG-55 Fence/Preplaster
CBR2024-0624	7742 PALENQUE ST	No	12:00	BLDG-33 Service Change/Upgr
CBR2023-3205	6925 QUIET COVE DR	No	9:00	BLDG-24 Rough/Topout

Tim Kersch 760-889-4520

CBC2021-0489	1205 AVIARA PKWY	No	12:00	BLDG-84 Rough Combo(14,24,
CBRA2022-0145	1205 AVIARA PKWY			BLDG-13 Shear Panels/HD (ok

CBRA2022-0145	1205 AVIARA PKWY			BLDG-14 Frame/Steel/Bolting/\
CBRA2022-0145	1205 AVIARA PKWY			BLDG-15 Roof/ReRoof (Patio)
CBRA2022-0145	1205 AVIARA PKWY			BLDG-16 Insulation
CBRA2022-0145	1205 AVIARA PKWY			BLDG-25 Water Heater/Vents
CBRA2022-0145	1205 AVIARA PKWY			BLDG-27 Shower Pan/Tubs
CBRA2022-0145	1205 AVIARA PKWY			BLDG-34 Rough Electrical
CBRA2022-0145	1205 AVIARA PKWY			BLDG-44 Rough/Ducts/Damper
CBC2023-0375	2548 CAMPBELL PL	Yes	AM	BLDG-14 Frame/Steel/Bolting/\
CBC2024-0047	5840 EL CAMINO REAL, # 106	No	11:00	BLDG-21 Underground/Underfl
CBC2023-0394	5927 GEIGER CT	No	10:30	BLDG-14 Frame/Steel/Bolting/\
CBR2022-1327	1380 LAUREL TREE LN	No	1:00	BLDG-34 Rough Electrical
CBR2022-1327	1380 LAUREL TREE LN			BLDG-97 Disabled Accessibility
CBC2023-0204	5806 VAN ALLEN WAY, # 100	No	10:00	BLDG-24 Rough/Topout
Tony Alvarado 760-331-8796				
CBR2024-0915	7104 ALMADEN LN	No	11:00	BLDG-34 Rough Electrical
CBR2024-0915	7104 ALMADEN LN			BLDG-Final Inspection
CBR2023-3948	2870 AVENIDA CEREZA	No	1:00	BLDG-Final Inspection
CBR2023-5381	3530 AVENIDA PANTERA	No	2:00	BLDG-43 Air Cond./Furnace Se
CBR2023-5381	3530 AVENIDA PANTERA			BLDG-Final Inspection
CBC2023-0395	7447 BATIQUITOS DR	No	11:00	BLDG-84 Rough Combo(14,24,
CBR2023-4295	3555 CAMINO CEREZA	No	1:00	BLDG-Final Inspection
CBR2024-0168	3555 CAMINO CEREZA			BLDG-Final Inspection
CBR2023-1326	4728 EDINBURGH DR	No	9:00	BLDG-Final Inspection
CBM2023-0015	7218 SAN RAMON	No	10:00	BLDG-Final Inspection
CBM2024-0007	7306 SANTA BARBARA	No	10:00	BLDG-75 Screened Enclosure
CBM2024-0007	7306 SANTA BARBARA			BLDG-Final Inspection
CBR2024-0709	3533 SIMSBURY CT	No	9:00	BLDG-Final Inspection

CBR2022-0773	2150 TWAIN AVE	No	8:00	BLDG-Final Inspection
CBR2024-0826	7022 VIA CALAFIA	No	12:00	BLDG-Final Inspection
CBC2023-0057	2834 WHIPTAIL LOOP	No	8:00	BLDG-12 Steel/Bond Beam